

1 / 21

FIG. 2




FIG. 17




FIG. 3




FIG. 18




FIG. 4a

FIG. 1




FIG. 19





FIG. 20




FIG. 4




FIG. 40




FIG. 5




FIG. 41




FIG. 6




FIG. 7




FIG. 8




FIG. 13




FIG. 14




FIG. 15




FIG. 11




FIG. 12





FIG. 16






FIG. 21




FIG. 22




FIG. 23




FIG. 24




FIG. 25




FIG. 26




FIG. 27




FIG. 28




FIG. 29




FIG. 30




FIG. 31




FIG. 33




FIG. 32




FIG. 26a




FIG. 26b




FIG. 26c




FIG. 26f




FIG. 26d





FIG. 26e






FIG. 34




FIG. 35





FIG. 36




FIG. 37




FIG. 38




FIG. 39

7/21






FIG. 45





FIG. 46





FIG. 47

FIG. 48





9/21

FIG. 49




FIG. 50




FIG. 52




FIG. 51




FIG. 53




FIG. 54




FIG. 55




FIG. 56




FIG. 57




FIG. 58




FIG. 59




FIG. 61





FIG. 60

FIG. 62




FIG. 63




FIG. 64




FIG. 65




FIG. 66





FIG. 67

FIG. 68




FIG. 69




FIG. 70




FIG. 71





FIG. 72






FIG. 70a




FIG. 70b




FIG. 70c




FIG. 70d




FIG. 73




FIG. 74




FIG. 75




FIG. 76




FIG. 77a




FIG. 77




FIG. 78




FIG. 79




FIG. 80




FIG. 81







FIG. 82





F I G. 84



+



FIG. 85




FIG. 86




FIG. 87




FIG. 88




FIG. 89




FIG. 90




FIG. 91




FIG. 92





FIG. 93





APPROVED O.G. FIG.  
CLASS SUBCLASS  
DRAFTSMAN  
+

20/21

FIG. 94a




FIG. 94b




FIG. 95




FIG. 96




FIG. 97





FIG. 98



+

FIG. 99




FIG. 100

